

Ninety-six Hour Work-Rest Timeline
For Captain Williamson
For Juneau MSO Investigation into the Grounding of the M/V LeConte
May 12, 2004

5/2/04: Approx. 0000-0245	2h 45min	Slept from Tenakee. Springs to Hoonah
Approx. 00305-0830	5h 25min	Slept from Hoonah through Auke Bay
Approx. 0830-1645	8h 15min	Worked: vessel ops, inspect., drill recording Docked ship.
Approx. 1645-2100	4h15min	Worked on ship's business. Watched movie. Rested with feet up and read.
Approx. 2245-0000	1h 15min	Read book.
5/3/04 Approx 0000-0200	2h 00min	Slept to Hoonah was called let mate do landing and departure.
Approx. 0230-0600	3h 30min	Slept to Angoon.
Approx. 0730-1445	7h 30min	Worked on paper work, worked out in ship's gym until called for Standby. On bridge from Broad I. to Sitka. Took a walk in Sitka. On bridge for narrows and depart.
Approx. 1445-1745	3h 00min	
Approx. 1745-2000	2h 15min	Had chow. Read some SMS material. Did some personal reading.
Approx. 2000-2230	2h 30min	Slept called at Pt. McCartney for Kake Arr.
5/4/04 Approx.0020-0340	2h 30min	Slept called at Beacon Pt. for Psg. Arr.
Approx. 0340-0400	0h 40min	Conned vessel to dock. Visit with terminal agents.
Approx. 0445-0505	0h 20min	Conned ship out of narrows.
Approx. 0510-0700	1h 50min	Read and napped.
Approx. 0700-0800	1h 00min	Worked out until called at Pt. McCartney
Approx. 0800-0945	1h 45min	On bridge during landing and departure.
Approx. 0945-1330	3h45min	Prepare for safety meeting. Make inspections of ship. Called for Angoon arr.
Approx. 1445-1645	2h 25min	Working with the office and Sperry Marine to get VHF-DSC radio for delivery for Friday.
Approx. 1645-1800		Call for Tenakee Springs and departure.
Approx. 1830-2100	2h 30min	Rested and Napped. Rec. Reading
Approx. 2100-2215	1h 15min	Up for Hoonah arrival.
Approx. 2230-2400	1h 30min	Slept.
5/5/04 Approx. 0001-0600	5h 59min	Slept until 0600 Auke Bay let go.
Approx. 0600-0850	4h 50min	Work on ships business and worked out.
Approx. 0850-1015	1h 25min	On bridge for arrival Hoonah. Continued ship's business work and inspections
Approx. 1015-1345	3h 30min	Work on ships business. SMS reading
Approx. 1345-1515	1h 30min	On bridge for arrival and depart. Angoon

	Approx. 1515-1745	2h 30min
	Approx. 1830-2015	1h 43min
	Approx. 2030-2340	3h 10min
	Approx. 2340-0000	0h 20min
5/6/04	Approx. 0001-0130	1h 30min
	Approx. 0140-0445	3h 05min
	Approx. 0445-0645	2h 00min
	Approx. 0645-1143	5h 58min
	Approx. 1143-1843	7h 00min
	Approx. 1843-2145	3h 02min
	Approx. 2145-2230	0h 45min
	Approx. 2230-2400	1h 30min
5/7/04	Approx. 0001-0245	2h 44min
	Approx. 0245	0h20min
	Approx. 0315-0700	3h 45min
	Approx. 0730-1000	2h 30min
	Approx. 1000-1745	7h 45min
	Approx. 1830-2050	2h 20min
	Approx. 2100-2200	1h 00min
5/8/04	Approx. 2200-2400	2h 00min
	Approx. 0001-0200	1h 59min
	Approx. 0200-0345	1h 45min
	Approx. 0345-0515	1h 30min
	Approx. 0515-0730	1h 15min
	Approx. 0730-1515	7h 45min
	Approx. 1515-1730	2h 15min
	Approx. 1730-1900	1h 30min
	Approx. 1900-2145	2h 45min
	Approx. 2145-2210	0h 25min
	Approx. 2210-2400	1h 50min
5/9/04	Approx. 0001-0145	1h 44min
	Approx. 0145	0h 25min
	Approx. 0200-0430	2h 30min
	Approx. 0430-0700	2h 30min

Approx. 0730-1130	4h 00min	Worked on ship's business and up for South Inian Pass.
Approx. 1130-1320	1h 50min	Continue to make daily inspections until arrival Pelcan.
Approx. 1320-1545	2h 25min	Went for walk in Pelican. Depart Pelican
Approx. 1715- 1730	0h 15min	Up for South Inian Pass.
Approx. 1800-2145	3h 45min	Read and slept until called for Auke Bay arrival.
Approx. 2145-2245	1h 00min	Call for arrival and departure Auke Bay.
Approx. 2300-2400	1h 00min	Slept.
5/10/04 Approx. 0001- 0630	6h 29min	Slept through Hoonah and called for Angoon arrival and departure.
Approx. 0630-0747	1h 17min	Arrival Angoon and departure.
Approx. 0747-0952	2h 05min	Depart Angoon workout, daily inspections, LeConte hard aground on Cozian Rcef.